



10/601,315

C07C

CUSTOMER NUMBER 25268

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: Call et al. Attorney Docket No. MESO0057
Patent No: 6,951,147 Group Art Unit: 2856
Issued: October 4, 2005 Examiner: Robert Raevis
Title: OPTIMIZING ROTARY IMPACT COLLECTORS

Certificate

FEB 14 2006

of Correction

NOTIFICATION OF ERRORS

Bellevue, Washington 98004

January 23, 2006

TO THE COMMISSIONER FOR PATENTS:

The following errors were found during a review of the above-referenced United States Letters Patent. These errors were either inadvertently made in the original application or occurred in the printing of the patent. Since the errors are of an obvious nature, a formal Certificate of Correction is not believed to be warranted at this time. Therefore, it is requested that this notification be placed in the U.S. Patent and Trademark Office file.

<u>Location in Patent</u>	<u>Error</u>
Column 1, line 49 & 50	"Dr äger" should read --Dräger--
Column 3, line 14	after "would" insert --be--
Column 4, line 28	after "between" delete "the"
Column 4, line 36	after "readily" delete "be"
Column 5, line 38	after "disposed" delete "to"
Column 6, line 62	"that," should read--that--
Column 7, line 6	after "is" delete "a"
Column 10, line 8	"16eand" should read --16e and--
Column 14, line 20	"are" should read --and--
Column 14, line 20	After "100a" delete "is"
Column 16, line 56	"than" should read --that--

Location in Patent

Error


Column 18, line 13

"examiners" should read --examines--

Column 36, line 11
(Claim 18, line 2)

After "and" delete "a"

Respectfully submitted,



Michael C. King
Registration No. 44,832

I hereby certify that this correspondence is being deposited with the U.S. Postal Service in a sealed envelope as first class mail with postage thereon fully prepaid addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, Virginia 22313-1450, on January 23, 2006.

Date: January 23, 2006

